

**M/T - 6 Speed MTM Difficulty Selecting Gears**  
**TRANSMISSION & [CLUTCH](#)**  
 TC002-01

September 14, 2001

Title:  
 6-SPEED MTM

Models:  
 '00 - '01 Celica GTS

Introduction

In order to assist drivers that have experienced difficulty selecting gears, production changes have been made to the [shift cables](#), shift select mechanism, and internal transaxle components.

Applicable Vehicles

^ 2000 - 2001 model year Celica GTS with 6 - Speed MTM.

MODEL	STARTING VIN
2001 Celica GTS, 6 Speed	JTDDY32T#10049042

Production Change Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	REPAIR MANUAL ILLUSTRATION SECTION MX(C60)
33205-20020	33205-20021	Shaft Sub-Assy, Gear Shift Fork No. 1	MX10
33232-12012	33232-20020	Head, Gear Shift, No. 1	
33244-20050	33244-20051	Shaft, Gear Shift Fork, No. 3	
33251-20060	33251-20080	Lever, Shift Inner No. 1	MX47
33266-20030	33266-20040	Shift Interlock Plate	
90501-18122	90501-18127	Spring, Compression, No. 1	
90501-26087	90501-27035	Spring, Shift & Select Lever Shaft	
33530-20780	33530-20790	Lever Assy, Shift	MX59
33820-2B540	33820-2B670	Cable Transmission Control Select	

Parts Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

Warranty Information